


# Eastern Corridor Segments II and III Village of Newtown Focus Area



### 2.2 VILLAGE OF NEWTOWN FOCUS AREA

The Village of Newtown Focus Area extends from the western border of the Village of Newtown to Little Dry Run and includes the business district of Newtown. A detailed roadway map of the Village of Newtown Focus Area is included in **Appendix 2.** 

### 2.2.1 Study Area Characteristics

The Village of Newtown features a neighborhood business district which extends along SR 32 from the western corporation limit to just east of intersection of SR 32 (Main Street) and Church Street and approximately one-third mile both north and south of the SR 32/Church Street intersection. The business district is pedestrian-friendly, having sidewalks along both sides of SR 32 through the business district. Land use to the east of the SR 32/Church Street intersection along SR 32 includes light manufacturing, commercial, institutional, and residential land uses. In addition, a major element in this area is an active quarry on the north side of SR 32. This area includes a link to the Little Miami Bike Trail, in addition to the Little Miami Golf Center. There are no planned transportation projects for this focus area listed on ODOT's Statewide Transportation Improvement Program (STIP) for FY 2016-2019 dated July 29, 2016.

### 2.2.2 Community Attributes Identified in the Focus Area Workshop

Sixteen (16) participants from the area and surrounding communities attended the Focus Area Workshop. Workshop participants identified community attributes which are important to the Village of Newtown area and should be considered throughout the transportation planning process. These features include: the small town feel; the village's rich history of the Prehistoric Native Americans who lived in the Little Miami River Valley prior to the settlement of Newtown; the natural resources in the surrounding area including the Little Miami Valley, hills, and the Little Miami River; the diversity of wildlife; the walkability of the community; the quaint business district; the diversity of housing; and recreational features, including the Little Miami Bike Trail and Little Miami Golf Course.

### 2.2.3 Transportation Needs

<u>Stakeholder Input</u>: Input on transportation needs within the Village of Newtown Focus Area were solicited from those who attended the Focus Area Workshop and through the online interactive survey. Comments received – which focus on safety, congestion, mobility, and access issues – are included in the Needs Analysis Table (see <u>Appendix 2</u>) and are summarized in following sections.

<u>Technical Studies</u>: Technical data was collected for the roadway network within the Village of Newtown Focus Area to identify areas of high crash rates, congestion, geometric deficiencies, and pedestrian usage. This information is provided for the roadway segments and intersections in the Needs Analysis Table (see <u>Appendix 2</u>) and summarized in following subsections.

#### 2.2.3.1 SR 32: Village of Newtown Corporation Limit to Church Street

This section of SR 32, which extends from the Village of Newtown's western boundary at Turpin Lane to the SR 32 (Main Street) intersection with Church Street, is approximately one-half mile long. This section of SR 32 (Main Street) consists of three lanes – one through lane in each direction and a center two-way left turn lane. There are sidewalks on both sides of the roadway and numerous

driveways for residences and businesses. The speed limit (55 mph west of Turpin Lane) is 35 mph between the Newtown corporation limit to Debolt Street and 25 mph between Debolt Street and to Miljoie Drive; east of Miljoie Drive, the speed limit is 35 mph.

<u>Stakeholder Input</u>: Of the 50 comments submitted for this segment, 43 identify congestion as a concern. Representative comments include:

- Congestion is worse during the evening rush hour (4 comments)
- Varying SR 32 speed limit through Newtown contributes to congestion (6 comments)
- Traffic signal timing contributes to traffic congestion (5 comments)
- Traffic signals should be replaced with smart lights (1 comment)
- Traffic signals should be coordinated between Newtown, Mariemont, and Fairfax (1 comment)
- Need a bypass around Newtown (1 comment)
- Widen SR 32 (5 comments)
- Poor street lighting is an issue (1 comment)

Six bike comments identify bicycle mobility and access issues in Newtown:

- Connect Newtown bike paths with Ohio to Erie Trail, Lunken bike paths, bikeway to downtown Cincinnati (3 comments)
- Cyclist safety is an issue due to 55 mph speed limit outside of the Village. (1 comment)
- Not enough bicycle and pedestrian facilities (1 comment)
- Need bike route along Newtown Road (1 comment)

One pedestrian comment identifies a need for a sidewalk/path to Clear Creek Park from Newtown.

Public transit comments identify the following needs:

- An accessible transit stop (1 comment)
- Bus service between Eastgate and Cincinnati (1 comment)
- Light rail from Eastgate to Fairfax (along SR 32), connecting to the Wasson Line, Oasis Line and to Riverfront Transit Center (1 comment)
- Additional bus service, including bus rapid transit (1 comment)

<u>Crash Data</u>: ODOT's crash screening did not identify this segment as an area of high hazard. Crash data indicates that five crashes occurred over the three-year period (2013 – 2015).

**LOS Analysis:** No level of service analysis was conducted for this segment; however, the travel time data indicates a 55% increase in the eastbound travel time during the PM peak-hour compared to the off-peak travel time indicating congestion during the PM peak-hour.

**Geometric Data:** No geometric deficiencies were identified along this segment.

**<u>Pedestrian Data</u>**: No pedestrian data is available for this segment.

#### 2.2.3.2 SR 32/Church Street Intersection

The SR 32/Church Street intersection represents the center of the Newtown business district, and is a four-leg, signalized intersection. Crosswalks connect the sidewalks on each corner of this intersection, which represents the center of Newtown's business district.



Figure 13. SR 32/Church Street Intersection

<u>Stakeholder Input</u>: Of the 54 roadway comments provided, 53 address congestion issues. Representative comments include:

- Signal timing is an issue (21 comments)
- Additional lanes are needed at this intersection (2 comments)
- A bypass around Newtown is needed (1 comment)
- Church Street skew contributes to driver confusion (1 comment)

#### Representative bike comments include:

- Need bikeway connections between 5-mile trail, Lunken, and downtown (3 comments)
- Need bike lanes in this area and better connectivity of the existing bike paths in Newtown with the Cincinnati Bike Trail, US 50, and SR 32 (1 comment)
- Need bikeway connection between the Anderson trail system and Little Miami Scenic Trail (1 comment)
- Need Marked bike lanes (2 comments)
- Need connection between Ivy Hills residential area and Little Miami Scenic Trail (1 comment)

#### Representative pedestrian comments include:

- Existing streetscape is not pedestrian-friendly (1 comment)
- Pedestrian access is unsafe (1 comment)
- A pedestrian signal is needed (1 comment)

Public transit comments identify the following needs:

- A bus stop (3 comments)
- A park-and-ride facility (1comment)
- Rail access (1 comment)
- More frequent bus service (1 comment)
- A Bus Rapid Transit (BRT) stop (2 comments)
- Public transit in Newtown (1 comment)

<u>Crash Data</u>: The ODOT crash screening did not identify this intersection as an area of high-hazard. Crash data indicates that 10 crashes occurred over the three-year period (2013-2015).

LOS Analysis: The HCS analysis indicates that the westbound through movement and northbound through movement are currently failing during the AM peak-hour. In the No Build opening year (2022) and No Build design year (2042) conditions, the failures are corrected due to the ODOT methodology of balancing delays for future intersection analyses. Balancing delays does create failure with the southbound left turn movement in the design year. This indicates that the failure of the eastbound left turn movement is likely due to a signal timing issue. It is anticipated that operational or minor intersection improvements are required for the existing, No Build opening year conditions and No Build design year conditions.



Eastbound SR 32 at Church Street (PM Peak)



Northbound Church Street at SR 32 (AM Peak)



Westbound SR 32 at Church Street (AM Peak)



Southbound Church Street at SR 32 (PM Peak)

To supplement the HCS analysis a queue study was conducted for the westbound and northbound approaches during the AM peak period and the eastbound, northbound, and southbound approaches during the PM peak period. The number of cars in the queue was recorded at the end of green for 15 minutes prior to the peak hour to 15 minutes after the peak-hour ended. The number of cars was translated to a length by assuming a queue length of 25 feet per vehicle. During the AM peak period the maximum westbound queue extended 1,750 feet back past the Round Bottom Road intersection and the maximum northbound queue extended 1,250 feet. During the PM peak period the maximum eastbound queue extended almost a half mile (2,400 feet) past the Newtown Corporate limits, the maximum northbound queue extended 1,100 feet, and the maximum southbound queue extended 1,200 feet. The recorded queues during the AM peak period are shown in Figures 14 and 15 and the recorded queues during the PM peak period are shown in Figures 16, 17, and 18.




Figure 14. Westbound SR 32 AM Peak Period Queues at Church Street




Figure 15. Northbound Church Street AM Peak Period Queues at SR 32




Figure 16. Eastbound SR 32 PM Peak Period Queues at Church Street




Figure 17. Southbound Church Street PM Peak Period Queues at SR 32




Figure 18. Northbound Church Street PM Peak Period Queues at SR 32

<u>Geometric Data</u>: The intersection sight distance is very poor due to obstruction by buildings on two corners of the intersection. Because this intersection is fully-controlled by a traffic signal, proper intersection sight distance is not required per *L&D Vol. 1.*; however, intersection sight distances for vehicles on SR 32 making right turns are 80 feet for eastbound traffic and 90 feet for westbound traffic. Both sight distances are less than the required 335 feet, and inhibit the ability for vehicles to execute right-turns during red signal phases.

**<u>Pedestrian Data</u>**: Forty-four (44) pedestrians were observed at the intersection during a 24-hour period recorded on December 9, 2015.

#### 2.2.3.3 SR 32: Church Street to Round Bottom Road

The section of Main Street (SR 32) between Church Street and Round Bottom Road is approximately one-third mile. In this section, the posted speed limit is 25 mph and the roadway is two lanes with a center two-way left turn lane. There are sidewalks along both sides of the roadway, as well as numerous business and residential driveways.

<u>Stakeholder Input</u>: Of the 37 comments submitted for this segment, 36 address roadway congestion. Representative comments include:

- Traffic signal timing is poor (1 comment)
- Varying speed limit on SR 32 through Newtown contributes to congestion (1 comment)
- Too many traffic signals and/or stop signs in this roadway segment (2 comment)
- Need a bypass around Newtown (1 comment)
- The road should be widened (2 comments)

Five bike comments include:

Need marked bicycle lanes (1 comment)

- Need bicycle connections to Eastgate and the Cincinnati Bike Trail (2 comments)
- Bike riding along SR 32 is not safe (2 comments)

Six comments identify public transit needs:

- Improve bus service, including expanded routes (3 comments)
- Provide light rail service (2 comments)
- Add a transit stop in the parking space near the former e-testing site (1 comment)

<u>Crash Data</u>: ODOT's crash screening did not identify this segment as an area of high hazard. Crash data indicates that two crashes occurred over the three-year period (2013 – 2015).

**LOS Analysis:** No level of service analysis was conducted for this segment; however, the travel time data indicates a 45% increase in the eastbound travel time during the PM peak-hour and a 35% increase in the in the westbound travel time during the AM peak-hour compared to the off-peak travel time indicating congestion during the AM and PM peak hours.

**Geometric Data:** No geometric deficiencies were identified along this segment.

**<u>Pedestrian Data</u>**: No pedestrian data is available for this segment.

#### 2.2.3.4 SR 32/Round Bottom Road/River Hills Drive Intersection

The SR 32/Round Bottom Road/River Hills Drive intersection is a five-leg, signalized intersection:



Figure 19. SR 32/Round Bottom Road/River Hills Drive Intersection

<u>Stakeholder Input</u>: Of the 29 roadway comments, 14 address congestion at this intersection and 9 address traffic signal timing. Representative comments include:

- Traffic signal phases are long (2 comments)
- Need a bypass around Newtown (2 comments)
- Improve signal timing (4 comments)
- The speed limit (25 mph) is too slow (2 comments)

One comment cites a need for better pedestrian access from Ivy Hills to Newtown. Two comments cite a need for improved bus service and light rail transit.

<u>Crash Data</u>: ODOT's crash screening did not identify this intersection as an area of high hazard. Data indicates that five crashes occurred over a three-year period (2013-2015).

LOS Analysis: The HCS analysis indicates that currently the westbound through movement is failing with a v/c ratio of 1.01 during the AM peak-hour and the southbound left turn movement is at capacity and the 95th percentile queue length for the movement is more than twice the storage length during the PM peak-hour. In the No Build opening year (2022) and No Build design year (2042) conditions, the westbound AM peak-hour failure is corrected due to the ODOT methodology of balancing delays for future intersection analyses. Balancing delays does not correct the southbound left turn movement failure during the PM peak-hour. Additionally, the eastbound through movement fails in the opening year with a v/c ratio of 1.02 and in the design year only gets worse with a v/c ratio of 1.09. It is anticipated that operational or minor intersection improvements are required for the existing, No Build opening year conditions, and No Build design year conditions.







Eastbound SR 32 at Round Bottom Road (PM Peak)

To supplement the HCS analysis a queue study was conducted for the westbound approach during the AM peak period and the eastbound and southbound approaches during the PM peak period. The number of cars in the queue was recorded at the end of green for 15 minutes prior to the peak hour to 15 minutes after the peak-hour ended. The number of cars was translated to a length by assuming a queue length of 25 feet per vehicle. During the AM peak period the maximum westbound queue extended 850 feet. During the PM peak period the maximum eastbound queue extended 1,250 feet and the maximum southbound queue extended 1,050 feet. The recorded queues during the AM peak period are shown in Figures 20 and the recorded queues during the PM peak period are shown in Figures 21 and 22:




Figure 20. Westbound SR 32 AM Peak Period Queues at Round Bottom Road




Figure 21. Eastbound SR 32 PM Peak Period Queues at Round Bottom Road




Figure 22: Southbound Round Bottom Road PM Peak Period Queues at SR 32

Geometric Data: As seen in Figure 19 (above), vehicles turning right onto SR 32 from Round Bottom Road are removed from the rest of the intersection. This right turn is stop-sign controlled, whereas all other intersection approaches are traffic signal-controlled. This right-turning movement has deficient intersection sight distance. The intersection sight distance for this movement is 290 feet looking left and the required sight distance is 335 feet. Although adequate intersection sight distance is not required at signalized intersections, the left intersection sight distance on River Hills Diver, the right intersection sight distance on Round Bottom Road, and the eastbound SR 32 stopping sight distance are all less than the 335-foot design standard for 30 mph design speed.

<u>Pedestrian Data</u>: One pedestrian was observed at the intersection during a 24-hour period recorded on December 9, 2015.

#### 2.2.3.5 SR 32: Round Bottom Road to Little Dry Run Road

The section of SR 32 between Round Bottom Road and Little Dry Run Road is approximately 0.78 mile in length. This section of roadway has two through lanes and a center two-way left turn lane. Just east of Round Bottom Road, the speed limit increases from 25 mph to 35 mph. The speed limit is raised again at Ivy Hills Place where it increases to 50 mph. There are no sidewalks in this section of SR 32.

**<u>Stakeholder Input</u>**: Of the 41 comments which address roadway issues, 35 concern congestion on this segment. Representative comments include:

- Lack of dedicated left-turn lanes exacerbate congestion (1 comment)
- Need four through-lanes and a center left-turn lane (1 comment)
- Need a route that avoids Newtown, Mariemont, and Fairfax (3 comments)
- The speed limit is an issue (1 comment)

Eight comments identify the following bicycle needs:

- A shared-use path from Little Dry Run Road to the Little Miami Scenic Trail (4 comments)
- A bike/pedestrian designated lane (2 comments)
- A connection between the Little Miami Scenic Trail and the Eastgate area (2 comments)

Six comments identify the following pedestrian needs:

- Sidewalk access along SR 32 from Little Dry Run Road to Newtown (4 comments)
- Sidewalk access to Newtown parks (1 comment)
- Pedestrian access from Little Dry Run Road to Round Bottom (1 comment)

Nine comments identify the following public transit needs:

- Bus route on SR 32 connecting Fairfax to Batavia (1 comment)
- Transit hub/express service (1 comment)
- Express Bus and park-and-ride to Uptown Area along SR 32 (1 comment)
- More transit options for Clermont County residents (1 comment)
- Metro Line (2 comments)
- Light rail (2 comments)
- Oasis commuter rail from Clermont County to the Cincinnati Riverfront (1 comment)

<u>Crash Data</u>: ODOT's crash screening did not identify this segment as an area of high hazard. Data indicates that 12 crashes occurred over the three-year period (2013-2015).

**LOS Analysis:** No level of service analysis was conducted for this segment; however, the travel time data indicates a 45% increase in the eastbound travel time during the PM peak-hour and a 35% increase in the in the westbound travel time during the AM peak-hour compared to the off-peak travel time indicating congestion during the AM and PM peak hours.

**Geometric Data:** No geometric deficiencies were identified along this segment.

**<u>Pedestrian Data</u>**: No pedestrian data is available for this segment.

#### 2.2.3.6 Round Bottom Road: SR 32 to Valley Avenue

Round Bottom Road is a two-lane undivided roadway which extends approximately 0.4 miles between its intersection with SR 32 at its southern terminus and its intersection with Valley Avenue at its northern terminus. Round Bottom Road has narrow shoulders and no sidewalks. There is an at-grade railroad crossing of Round Bottom Road approximately 0.1 miles north of the SR 32 (Main Street) intersection.

**<u>Stakeholder Input</u>**: There are eleven roadway comments for Round Bottom Road between SR 32 and Valley Avenue. These comments identify the following issues:

- Roadway congestion (9 comments)
- Safety is a concern
- Improve Round Bottom Road to function as an alternative route through the area

Eleven bikeway comments were provided:

- Safety of bicyclists on Round Bottom Road is a concern (6 comments)
- Marked bike lanes or a multi-modal path is needed to discourage bicycle traffic along Round Bottom Road (5 comments).

Three public transit comments identify the following needs:

- More rail and local bus access (1 comment)
- A park and ride in the area (2 comments)

<u>Crash Data</u>: ODOT's crash screening did not identify this segment as an area of high hazard. Crash data indicates that no crashes occurred over the three-year period (2013 – 2015).

**LOS Analysis:** No level of service analysis was conducted for this segment.

**Geometric Data:** No geometric deficiencies were identified along this segment.

**<u>Pedestrian Data:</u>** No pedestrian data is available for this segment.

### 2.2.3.7 Round Bottom Road/Valley Avenue Intersection

The Round Bottom Road/Valley Avenue intersection is a signalized T-intersection:



Figure 23. Round Bottom Road/Valley Avenue Intersection

<u>Stakeholder Input</u>: There are no public comments for the Round Bottom Road/Valley Avenue Intersection.

<u>Crash Data</u>: ODOT's crash screening did not identify this intersection as an area of high hazard. Crash data indicates that no crashes occurred over the three-year period (2013 – 2015).

<u>LOS Analysis:</u> The HCS analysis indicates that the northbound left turn movement is currently failing during the AM peak-hour with a v/c ratio of 1.02. In the No Build opening year (2022) and No Build design year (2042) conditions the northbound left turn continues to fail as well as the eastbound right turn movement. It is anticipated that operational or minor intersection improvements are required for the existing, No Build opening year conditions, and No Build design year conditions.

**Geometric Data**: No geometric deficiencies were identified at this intersection.

<u>Pedestrian Data</u>: Four pedestrians were observed at the intersection during a 24-hour period recorded on December 9, 2015.

### 2.2.3.8 Round Bottom Road: Valley Avenue to Broadwell Road

Round Bottom Road is a two-lane undivided roadway which extends approximately 1.6 miles between its intersection with Valley Avenue at its southern terminus and its intersection with Broadwell Road at its northern terminus. Round Bottom Road has narrow shoulders, no sidewalks, and no auxiliary turn lanes are present for the entire length of the segment.

<u>Stakeholder Input</u>: Two comments identify congestion as an issue on Round Bottom Road as follows:

- Poor signal timing and slow speed limit (25 mph)
- Too much traffic on this road; concerns about the impact on traffic from the limestone mine coming to the area

Bike comments include the following:

- Round Bottom Road is too narrow for bike traffic (1 comment)
- A bike lane/path is needed along Round Bottom Road (2 comments)

One pedestrian comment identifies the need for a sidewalk along Round Bottom Road because the roadway is too dangerous for pedestrians to walk along.

<u>Crash Data</u>: ODOT's crash screening did not identify this segment as an area of high hazard. Data indicates that seven crashes occurred over the three-year period (2013 – 2015).

**LOS Analysis:** No level of service analysis was conducted for this segment.

<u>Geometric Data</u>: There is one deficient horizontal curve in this segment. The existing curve in front of Natorp's Nursery has a degree of curvature of 8°50' compared to the allowable 8°00' for 45 mph.

**<u>Pedestrian Data:</u>** No pedestrian data is available for this segment.

#### 2.2.3.9 Valley Avenue: Church Street to Round Bottom Road

Valley Avenue is a two-lane roadway which extends approximately 0.3 miles between its intersection with Church Street at its western terminus and its intersection with Round Bottom Road at its eastern terminus. Valley Avenue, which is posted as 25 mph, has sidewalks on both sides of the roadway, as well as numerous driveways for businesses and residences. About 250 feet west

of the Round Bottom intersection, there is a mid-block crosswalk. At the Church Street/Valley Avenue intersection, Valley Avenue terminates as the roadway becomes the access road into the Great Miami Golf Center. At its eastern terminus, Valley Avenue intersects with Round Bottom Road in a signalized T- intersection.

<u>Stakeholder Input</u>: Seven public comments address roadway issues on Valley Avenue between Church Street and Round Bottom Road. Each of these comments concern congestion issues on Valley Avenue. Representative comments include:

- There are back-ups on Valley to get to SR 32 (2 comments)
- The signal at Valley and Church and speed limit (25 mph) are issues (2 comments)

<u>Crash Data</u>: ODOT's crash screening did not identify this segment as an area of high hazard. Crash data indicates that three crashes occurred over the three-year period (2013-2015).

**LOS Analysis:** No level of service analysis was conducted for this segment.

**Geometric Data:** No geometric deficiencies were identified along this segment.

**Pedestrian Data:** No pedestrian data is available for this segment.

#### 2.2.3.10 Church Street: SR 32 to Valley Avenue

This section of Church Street (Newtown Road), which extends approximately one-half mile from SR 32 (Main Street) to Valley Avenue, is two lanes with sidewalks along both sides of the road. In addition, there are numerous driveways for businesses and residences along this section of road. This section is posted for a speed of 25 mph. There is an at-grade railroad crossing of Church Street approximately one-quarter mile from the SR 32 (Main Street)/Church Street intersection.

<u>Stakeholder Input</u>: Fourteen comments concern roadway issues on Church Street between SR 32 and Valley Avenue. Of these comments, eleven identify congestion issues and several address issues with the at-grade railroad crossing. Representative comments include:

- A bypass of Newtown is needed (1 comment)
- There are problems at the following four intersections: 1) Valley/Church; 2) Valley/Round Bottom; 3) Church/Batavia; and 4) Batavia/Round Bottom (1 comment)
- Signal improvements or a roundabout should be considered at the SR 32/Church Street intersection (1 comment)
- The at-grade rail crossing is not level and should be repaired (1 comment)
- Train schedules should be posted near the railroad crossing since the train often delays traffic in this area (1 comment)

#### Five bike comments include:

- Safety concerns for bicyclists sharing roads in Newtown (1 comment)
- Designated bike lanes or bike paths are needed (1 comment)
- A bikeway connection is needed between Newtown and area bike paths such as the path neat Columbia Parkway and 5-mile Trail (2 comments)

 A connecting bike path should be constructed from the Little Miami Scenic Bike Trail and Newtown and Clear Creek Park (1 comment)

Eight public transit comments identify the following needs:

- Rail service is needed (4 comments)
- Expanded bus service is needed (1 comment)
- An accessible transit stop is needed (2 comments)
- The expansion of public transit will reduce vehicular traffic on the roads (1 comment)

<u>Crash Data</u>: ODOT's crash screening did not identify this segment as an area of high hazard. Data indicates that three crashes occurred over a three-year period (2013-2015).

**LOS Analysis:** No level of service analysis was conducted for this segment; however, the travel time data indicates a 40% increase in the northbound travel time during the AM peak-hour and a 50% increase in the in the southbound travel time during the PM peak-hour compared to the off-peak travel time indicating congestion during the AM and PM peak hours.

<u>Geometric Data</u>: The crest vertical curve at the railroad crossing on this segment of Church Street has a substandard k-value for its design speed (25 mph). The actual k-value for this segment of Church Street is 10; the required k-value is 12.

**<u>Pedestrian Data</u>**: No pedestrian data is available for this segment.

### 2.2.3.11 Church Street (Newtown Road)/Valley Avenue Intersection

The Church Street/Valley Avenue intersection is a signalized four-leg intersection. The northwest leg of this intersection serves as the entrance road to the Little Miami Golf Center:



Figure 24. Church Street/Valley Avenue Intersection

**Stakeholder Input:** Four roadway comments address congestion at this intersection. They are:

- Signal timing is an issue (3 comments)
- The posted speed through this area (25 mph) is too slow (1 comment)

<u>Crash Data</u>: ODOT's crash screening did not identify this intersection as an area of high hazard. Crash data indicates that no crashes occurred over the three-year period (2013 – 2015).

**LOS Analysis:** The HCS analysis indicates that no deficiencies currently exist at the intersection. In the No Build opening year (2022) the southbound left turn lane 95th percentile queue length for the movement is more than twice the storage length during the PM peak-hour. In No Build design year (2042) conditions the southbound left turn movement fails with a v/c ratio of 1.04. No intersection improvements are required for the exiting conditions, but it is anticipated that operational or minor intersection improvements are required for the No Build opening year and No Build design year conditions.

**Geometric Data:** No geometric deficiencies were identified along this segment.

<u>Pedestrian Data</u>: Twenty-seven (27) pedestrians were observed at the intersection during a 24-hour period recorded on December 9, 2015.

#### 2.2.3.12 Church Street/Newtown Road: Valley Avenue to US 50

Church Street between Valley Avenue and US 50 is two lanes. There are no sidewalks along this roadway and the speed limit is posted at 35 mph.

**Stakeholder Comments:** Twenty-two comments were provided for the section of Church Street (Newtown Road) between Valley Avenue and US 50, of which 18 indicate that congestion is the predominant roadway concern on Church Street between Valley and US 50. Other concerns identify roadway repair and access issue. Representative comments include:

- Congestion makes access/egress to/from parking lots along Newtown Road difficult (1 comment)
- Church Street should be widened to four lanes from Valley to US 50 (1 comment)
- A bypass around Newtown is needed (1 comment)
- The current bridge over the Little Miami River is not big enough and needs to be replaced (1 comment)
- There should be no roadway expansion in this area and no additional impact on the Little Miami River (1 comment)
- Road repair is needed (1 comment)

Ten comments identify the need for improved bike access in this area through bike paths and/or lanes. Specific bikeway connections that are recommended include:

- Finish bike trail to Cincinnati (1 comment)
- Connect the Little Miami Trail to Downtown and also through Mariemont, Fairfax, and Hyde Park (1 comment)

- Connect the Little Miami Trail to the Murray Road Trail (1 comment)
- Connect bike trail from Newtown bridge to Downtown and connect to Miami Bluff Road (1 comment)
- Connect bike path to Wasson Way (1 comment)

Two comments cite a need for a sidewalk and pedestrian/bike lanes, and three comments identify the following public transit needs:

- The need for bus service (1 comment)
- The need for a park and ride (1 comment)
- Public transit is needed to serve local bars and restaurants (1 comment)

<u>Crash Data</u>: ODOT's crash screening did not identify this segment as an area of high hazard. Crash data indicates that six crashes occurred over the three-year period (2013 – 2015).

**LOS Analysis:** No level of service analysis was conducted for this segment; however, the travel time data indicates a 40% increase in the northbound travel time during the AM peak-hour and a 50% increase in the in the southbound travel time during the PM peak-hour compared to the off-peak travel time indicating congestion during the AM and PM peak hours.

**Geometric Data:** No geometric deficiencies were identified along this segment.

**<u>Pedestrian Data</u>**: No pedestrian data is available for this segment.

### 2.2.4 Newtown Village Focus Area Needs Analysis

Based on the results of the technical studies, as well as the extensive public input received from the Focus Area Workshops, online interactive survey, and other public outreach efforts, the primary and secondary needs of the transportation network with the Village of Newtown Focus Area were identified (primary needs are needs that will be addressed by this project; secondary needs are needs that may be addressed by this project). The input used in the needs analysis is included in **Appendix 2**. The primary and secondary needs are presented in **Table 10** below.

Table 10: Village of Newton Focus Area Needs Analysis

Primary Needs	Secondary Needs
SR 32: West Corporation Limits to Church Street	
Address eastbound peak-hour delays	Address bicycle connectivity
SR 32/Church Street Intersection	
Address capacity issues and long queues on all approaches	None
SR 32: Church Street to Round Bottom Road	
Address westbound AM peak-hour and eastbound PM peak-hour delays	Address bicycle connectivity
SR 32/Round Bottom Road Intersection	

Primary Needs	Secondary Needs
Address capacity issues and long queues on SR 32 and Round Bottom Road approaches	Address deficient sight distance at intersection
SR 32: Round Bottom Road to Little Dry Run Road	
<ul> <li>Address westbound AM peak-hour and eastbound PM peak-hour delays</li> <li>Address pedestrian connectivity to east corporation limit</li> </ul>	Address bicycle connectivity     Support access to future transit connections
Round Bottom Road: SR 32 to Valley Avenue	
Address congestion	Enhance bicycle connectivity
Round Bottom Road/Valley Avenue Intersection	
Address capacity issues with northbound left-turn movement and eastbound approach	None
Round Bottom Road: Valley Avenue to Broadwell Road	
None	Correct deficient roadway curve near Natorp's Nursery
	Enhance bicycle connectivity
Valley Avenue	
None	None
Church Street: SR 32 to Valley Avenue	
Address northbound AM and southbound PM peak- hour delays	<ul> <li>Address roadway grades at railroad crossing</li> <li>Enhance bicycle connectivity</li> <li>Support access to future transit connections</li> </ul>
Church Street/Valley Avenue Intersection	
Address capacity issues for southbound left-turn movement	None
Newtown Road (Church Street): Valley Avenue to US 50	
Address northbound AM and southbound PM peak- hour dealys	None

# APPENDIX 2 NEWTOWN VILLAGE AREA





Notes
1. Coordinate System: NAD 1983 StatePlane Ohio South FIPS 3402 Feet
2. Base features: produced from project design elements.
3. Base Imagery: Orthoimagery - OGRIP-OSIP II, 2012.

Legend

Ancor SR 32 Hill Area

Newtown Village Area SR 125-SR 32 Area

US 50 Corridor Area

**\*** LOS Analysis Intersection

++ LOS Analysis Roadway Segment

2,000 Feet 1,000

1:14,000 (At original document size of 11x17)



Hamilton and Clermoni Counties, Ohio

173620069 Prepared by BL on 2016-11-21

Client/Project
Ohio Department of Transportation, District 8
Transportation Needs Analysis
Eastern corridor Segments II and III

Focus Area Detail Village of Newtown Focus Area:

**Newtown Village** 

at 125, 32, and Eastern Ave.

Community Attributes Identified in the Focus

Area Workshop:

Participants at the Focus Area Workshop identified the following community attributes for the Village of Newtown and surrounding area: an important history; the small town feel; environmental assets including the valley, hills, trails and the Little Miami River; accessibility to Downtown, Eastgate, and Kenwood; the diversity of wildlife; its walkability and bike trail; the nice golf course, good businesses, and the diversity of housing (moderate to high end houses).

**HCS Analysis** Existing Year 2015 Opening Year 2022 Design Year 2042 <u>Travel Time</u> <u>Queue Analysis</u> <u>Geometric Analysis</u> <u>Primary Needs</u> <u>Transportation Concern</u> <u>MetroQuest Comments</u> Workshop Comments <u>Safety</u> Secondary Needs SR 32: West Corp Line to Church Congestion Bypass around or allow to go into town; need bypass around The morning traffic east to west is bad. In the 5 crashes on the segment from 2013 | 55% increase | PM peak-hour Address eastbound PM peak-hour No deficiencies afternoon, it's west to east. through 2015. Not identified as a in the EB travel queues from the delays. high hazard location by ODOT Church Street time during Reduce congestion here and through Mariemont. Not enough Fix the lights and have smart lights. the PM peakscreening. intersection routes to downtown/uptown. mpacts the Newtown is congested, and going from 55 mph to 35 or 25 compared to eastbound and then back up again is a travel frustration. the off-peak direction of this Traffic signal issue. Through Newtown the lights are fine in travel time. segment. the morning but going home the lights' timing needs to be fixed from the UDF light (Church St) all the way to Little Dry Congestion during evening commute, backed-up from soccer fields all the way to Newtown Road. Unacceptable. Newtown is a big bottle neck. More businesses would come if better traffic patterns exist. Like a connect to Five Mile from SR 32 and better access to Columbia Parkway. Traffic delays. (17 pins) This is where congestion is worst during evening rush hour. Widen the highway and install light rail service in the center of a divided highway. The bottleneck is debilitating. Slows to 35-25 MPH. Traffic lights are slow. Roads are small. Too much congestion. Speeds artificially deflated. Newtown is a place to avoid period. Businesses are actually hurt by the congestion. SR 32 needs to be widened. Single lane with the rush hour volume causes congestion. Major congestion during peak hours; low speeds (25 MPH) in Narrow, one lane congestion - nightmare. Slow speed limit causes even more congestion. I use side streets when possible. A direct "no stop light option" to Beechmont Levy is highly desired. 10+ minutes at 5:00 pm to drive through Main Street that is about 1 mile long. In the evenings, there's a backup on SR 32 heading eastbound. Driving through Newtown slows traffic down. Adding a lane, increasing speed limit or bypassing Newtown is desirable. Traffic police also slow it down. Too few lanes. The speed limit goes down way too far. Please provide streets where cars can travel at least 40 MPH through the Heavy congestion during peak hours; lowered speed limits/shifts. Throughout Newtown, the lights are fine in the morning but going home, the lights' timing needs to be better from the UDF light all the way to Little Dry Run. This area is a nightmare. I avoid it at all costs. Speed limit is outdated. Signals are not connected. Narrowness of area going toward bridge and Lunken. Safety Frequent Accidents. Access Need for additional travel lanes through Newtown with pedestrian access. Eastgate must be connected to the greater area's east of Cincinnati. Many people are missing the opportunity for easy access to shopping that Eastgate offers. Coordinate signals between Mariemont, Fairfax, and Other Street lighting issue. Mobility Bike route along Newtown Road. Concerns about not having enough bicycle and Address bicycle connectivity. n/a n/a none pedestrian facilities. Access/Mobility Complete connectivity to downtown Cincinnati. Access Access to Lunken and then to a downtown bike route. This corridor should include facilities for bikes that connects into the Ohio to Erie Trail both at Newtown Rd and US 50 and

**HCS Analysis** 

Transportation Concorn	MetroQuest Comments	Workshop Comments	Existing Year 2015	HCS Analysis Opening Year 2022	Dosign Voor 2012	<u>Safety</u>	Travel Time	Queue Analysis	Goometric Analysis	Primary Needs	Secondary Needs
<u>Transportation Concern</u> Safety		On SR 32, the speed limit outside the village is too fast		Opening Year 2022	Design Year 2042	Salety	Travel Time	Queue Analysis	Geometric Analysis	Filliary Needs	Secondary Needs
Surcey		for the amount of pedestrian and bicycle facilities,									
		business entry's, and park entrances.									
Access	There's a large park and no real bike or pedestrian friendly		n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
	way to get to it. Smacks of ill suburban planning.										
Mobility Access	Need a sidewalk  Need accessible transit stop.	none	n/a	n/a	n/a	n/2	n/a	n/a	n/a	none	none
	·		liva	ii/ a	lily a	liya	lily a	lily a	lily a	Hone	none
Mobility	Rubber tire transit needs to be established between Eastgate and Cincinnati.	Bus services (BRT) is a great idea.									
	The current public transportation offerings for the entire	_									
	metro area (including the study area) are extremely deficient.										
	Our region's growth will continue to be hampered by this fact	t.									
	I consider myself to be fiscally conservative but very much believe that [cut-off].										
	Advance commuter rail/light rail from Eastgate to Fairfax	-									
	along SR 32 alignment, then to multi-modal hub in Fairfax										
	area allowing connection to Wasson Line and Oasis Line										
	segments to Riverfront Transit Center.										
Church / Main (SR 32) Inte											
Congestion			AM WBT = LOS F, v/c 1.06	AM SBL = Queue > Storage	AM WBT = LOS F, v/c 1.00	10 crashes at intersection from 2013	3 n/a		No deficiencies	Address capacity issues and long	none
	Need more capacity, especially during rush hour.  Wait times at this light are long. Especially southbound	better signal timing.	AM NBT = LOS F, v/c 0.94		AM SBL = Queue > Storage AM SBL = LOS F, v/c 0.89	through 2015. Not identified as a high hazard location by ODOT		Max Queue WB = 1750', at		queues on all approaches	
	weekday evenings.				552 2531, 7, 6 0.05	screening.		times backs			
	Traffic Signal Issue. Streamline lights in Newtown. Add turn							through the			
	lanes or something for the truck traffic into the asphalt and							Round Bottom			
	gravel pits.							intersection NB = 1,250'			
	Consistent traffic delays getting through this intersection during morning and evening rush hour if trying to move							1,230			
	north/south. SR 32 gets all the green time.										
	The light at 32 and Church gets really backed up if there is an							PM Peak-Hour	1		
	accident on Beechmont Levee or Wooster Pike. If there's not							Max Queue			
	an accident, traffic is not bad.							EB = 2,400'			
	Traffic Signal Issue. Traffic flow is impeded by light. Not							NB = 1,100' SB = 1,250'			
	timed efficiently. (5 pins)  Traffic Signal Issue: This traffic signal is poorly managed. I've							35 - 1,230			
	sat at this light for more than 20 minutes while on SR 32										
	(approximately 5-10 cycles) with traffic eastbound backed up										
	to the soccer fields and almost to Clough Pike.										
	NB Church St. is very congested during morning rush hour.										
	The usual wait is multiple signal sequences at SR 32.  Traffic Signal Issue. Traffic at this light gets backed up in the										
	afternoon. (2 pins)										
	The intersection of SR 32 and Main/Church is a pinch point fo	or .									
	the entire area. (21 pins)										
	A direct "no stop light option" to Beechmont Levee is highly desired.										
	Heavy congestion during peak hours; lowered speed	-									
	limits/shifts.(4 pins)										
	Newtown is a huge bottleneck. There are very few businesses	S									
	thru here. The road needs expanded. This could be a										
	convenient road for those that travel between downtown and the east side.										
	Congestion through Main Street; could use a bypass to										
	increase mobility with higher speed allowance.										
	The timing of this stoplight needs to be better during rush										
	hours. (4 pins)  Poorly timed lights. Single lane in each direction leads to long	7									
	delays.										
	Traffic Signal Issue. It is too long of a wait.										
	SR 32 needs to be upgraded and widened.										
	The 25 mile and hour speed limit and the volume of cars										
Safety	makes this intersection super congested during rush hour	Because the main intersection (Church and Main) is									
		not 90 degrees, it is hard to know what's supposed to									
		happen.									
Access	,	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
	downtown bike route. (3 pins)										
	Need better bicycle space on roads through Newtown to connect to Cincinnati Bike Trail/Rt. 50 and SR 32.										
	Another great little town for biking. If the city father's would										
	spend more time in developing their place, like Loveland, they										
	would be content with traffic moving faster and easier thru										
	town and still make their town a showplace.										

				<b>HCS Analysis</b>							
Transportation Concern		Workshop Comments	Existing Year 2015	Opening Year 2022	Design Year 2042	Safety	Travel Time	Queue Analysis	Geometric Analysis	Primary Needs	Secondary Needs
	If the Anderson trail system connected to Newtown, it would allow direct bicycle access to the Little Miami Trail and										
	encourage visitors to several shops/businesses in Newtown.										
	Need marked bike lanes. (2 pins)  Options to connect Ivy Hills to Little Miami Bike Path.	_									
	Options to connect by this to little Manii Bike ratii.										
Safety	The Village of Newtown is a pedestrian-friendly area. It	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
	should remain as such. Possible to build a skywalk here? The main street in Newtown does not seem designed to	_									
	encourage foot traffic. Part of this is due to the buildings										
	themselves, but part feels like it is due to the streetscaping.										
	Safety concern. Pedestrian signal issue.	_									
	Maintain inviting pedestrian access for Newtown.	_									
Access/Mobility	Closest bus stop is a mile away.	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
	There is currently no public transit in Village of Newtown.  Need accessible transit stop. (2 pins)	-									
	Need park and ride.										
Mobility	Would love to see light rail.	_									
Access	BRT stop. (2 pins)  More service-weekends, evenings, frequency.	-									
SR 32: Church to Round B											
Congestion	Congestion issue. (23 pins)	none	n/a	n/a	n/a	2 crashes along segment from 2013			No deficiencies	Address westbound AM peak-hour	
	One row each way; speed trap. (2 pins)					through 2015. Not identified as a		queues from the		and eastbound PM peak-hour delays.	
	Traffic Signal Issue - Too many signals in this section.  The mess of 3250 mph to 35 mph to 25 mph.	-				high hazard location by ODOT screening.	time during the PM peak-	Church Street intersection			
	Too much congestion in Newtown even on weekends. A						hour and a	impacts the			
	bypass is needed.	_					travel time during the AM peak-hour compared to the off-peak	westbound direction of this			
	Excessive congestion in mornings and evening rush hours. (4 pins)							segment. PM			
	Speed limits and traffic patterns through Newtown are an							peak-hour	20		
	impediment.  Backed up traffic through newtown; congestion is horrible. I	-						queues from the Round Bottom			
	don't have a solution other than widening the road							Road intersection	n		
	Heavy traffic; slow throughout because it's only 2 lanes through town and 25 miles and hour with several stop signs.						travel time.	impacts the eastbound			
	A nightmare for peak traffic.							direction of this			
	Slow throughout because it's only 2 lanes through town and							segment.			
	25 miles and hour with several stop signs. A nightmare for peak traffic										
Access	Missing Connection. In general, I would like a quicker way to	-									
	access the central area of Cincinnati from Eastgate without										
	having to drive all the way north on 275/71 or south 275/471										
Access	Bicycle-Pedestrian path connection to Eastgate.	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	Address bicycle connectivity.
Mobility	Need better bicycle space on roads through Newtown to										
	connect to Cincinnati Bike Trail/Rt. 50 and Rt. 32	_									
Safety	Need marked bike lanes.  No safe riding areas.	-									
,	It is not safe for cyclists, nor safe for area children. If there										
	was a more safe bike and walking area, there would be fewer										
Mobility	Enhance existing bus routes to provide better service for	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
	commuters. (2 pins)										
Access/Mobility	Need bus service.  Use light rail on the railways through this small town	-									
Access/Wobility	connecting to downtown and out to Batavia.										
	Light rail downtown.										
	Use parking space near former exhaust-testing site for riders to downtown or other major places of employment.										
	Light-rail going through here with stops in downtown										
	Newtown. The tracks could be in the center of a divided										
Round Bottom / SR 32 Int	highway										
Congestion	Traffic Signal Issue. (5 pins)	none	AM WBT = LOS F, v/c 1.01	PM SBL = Queue > Storage	PM SBL = Queue > Storage	5 crashes at intersection from 2013	n/a	AM Peak-Hour	Right on Red (SB	Address capacity issues and long	Address deficient sight distance at
	Congestion issue. (5 pins)		PM SBL = Queue > Storage	PM EBT = LOS F, v/c 1.02	PM SBL = LOS F, v/c 1.08	through 2015. Not identified as a		Max Queue	Roundbottom to WB	queues on SR 32 and Round Bottom	intersection
	Slows to 25 mph. Traffic lights are slow. Roads are small.				PM EBT = LOS F, v/c 1.09	high hazard location by ODOT		WB = 850'	32) deficient. Poor	Road approaches.	
	Too much congestion. (2 pins)  Slow traffic through Newtown creates congestion. Should					screening.		PM Peak-Hour	intersection sight distance on		
	have a bypass route around Newtown for through traffic.							Max Queue	Roundbottom		
	Intersection has improved significantly but it still gets backed up all through Newtown.							EB = 1,250' SB = 1,050'	because of fountain in	וו	
	Poorly timed lights. Single lane in each direction leads to long	3						36 - 1,030	median island and cars parked at Village		
	i dell'y annea il girle i dine il daesi an estient i daes te iong										

				HCS Analysis							
Transportation Concern		Workshop Comments	Existing Year 2015	Opening Year 2022	Design Year 2042	Safety	Travel Time	Queue Analysis	Geometric Analysis	Primary Needs	Secondary Needs
	This congestion is causing too much traffic on Clough Pike.										
	People from Amelia and beyond use Clough Pike instead of SR										
	Timing of lights are not set correctly and is always clogged up	1									
	in this area. Takes 10 minutes to travel once you enter										
	Newtown to go a little over one mile.										
	Often backs up here.	4									
	Congestion waiting to get onto 32. (4 pins)  Driving through Newtown is very slow. A bypass would	1									
	greatly improve travel time										
	Traffic backup at traffic light and slow speed limit through	1									
	Newtown	_									
Access	State highway with 25 mph speed limit is frustrating Limit access to SR 32 from 275 to Red Bank for reduction in	4									
Access	east-west travel time and conflict of through travel with local										
	travel. Provide interchanges at critical crossroads to afford										
	access to local business districts.										
C-f-+.	Access Issue. (2 pins)	-									
Safety Access	Needs repair.  Better connection (pedestrian) from Ivy Hills to Newtown.	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
Mobility	Need bus service.	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
	If there was a divided multi-lane highway going through here										
	with light-rail going down the middle, I think this would be a										
	major improvement in the area.										
SR 32: Round Bottom to L											
Congestion	,	none	n/a	n/a	n/a	12 crashes along segment from 2013			No deficiencies	Address westbound AM peak-hour	
	outdated. Signals are not connected.	4				through 2015. Not identified as a high hazard location by ODOT		queues from the		and eastbound PM peak-hour delays.	
	Make four lanes. (3 pins)  Congestion issue. (17 pins)	1				screening.		Round Bottom Road intersection			
	Backed up with traffic through Newtown. (2 pins)	1				Jorden Marie	hour and a	impacts the			
	Too much traffic for the two-lane road. Can't be avoided for	1					35% increase	westbound			
	anything local.	_						direction of this			
	Need a route to avoid traveling through Newtown, Mariemont, and Fairfax.						travel time during the AM	segment. PM			
	Traffic signal issue, cycle length too long. [pin at Ivy Hills	1					_	queues from the			
	Drive/SR 32]							Little Dry Run			
	There should (must) be an alternate option versus going							intersection			
	through Newtown. It's terrible.	-					travel time.	impacts the			
	This is a two-lane road. If someone is turning left, it does not take very long for there to be a traffic problem.							eastbound direction of this			
	This should be four lanes or at minimum have a dedicated	1						segment.			
	turn lane in the middle. Traffic backs up and if someone is										
	turning left it can be a ten minute affair.	_									
	Afternoon it takes too much time to traverse Newtown.	-									
	Newtown seems to be a speed trap. I avoid this section if possible. If the town were more inviting I may visit more										
	often.										
	This is always backed up in morning rush hour. I sometimes										
	add 15 extra minutes to get through Newtown.										
	Bad congestion  Need to widen road										
	Turn lanes on SR 32 around Newtown										
Access	Need a high speed road that avoids Newtown and connects										
	SR 32 to US 50 (at Red Bank).										
	Getting from here to Mariemont, Kenwood and beyond.  No quick way to get to Blue Ash.										
Safety	Air pollution and noise pollution danger throughout the										
.,	designated areas.										
	Too many bikes on SR 32 between Little Dry Run and										
	Newtown. Too tight an area for bikes and big trucks.	4									
	Frequent Accidents.  Traffic and cops watching for speeders										
Mobility		none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	Address bicycle connectivity.
	path in Newtown. (4 pins)										
A 0.00	Bike/Walking designated lane.										
Access	Connect Little Miami Scenic Trail with Eastgate Area. (2 pins)										
Safety	Need marked bike lanes; no marked lanes all the way thru										
Mobility		none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	Address pedestrian connectivity to	none
	cbd. (4 pins)									east corp limit.	
Access	Access to parks.										
	Pedestrian access from Little Dry Run to Round Bottom.										
Access/Mobility	I'd like to see a bus that connected Fairfax to Batavia, directly	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	Support access to future transit
Mobility	up 32.  Provide a transit hub/express service.	-									connections.

				<b>HCS Analysis</b>							
Transportation Concern	MetroQuest Comments	Workshop Comments	Existing Year 2015	Opening Year 2022	Design Year 2042	<u>Safety</u>	Travel Time	Queue Analysis	Geometric Analysis	Primary Needs	Secondary Needs
	Metro line.  Express Transit and Park&Rides to Uptown Area (Not	-									
	Downtown!) along 32.										
	More public transit options for people in Clermont Co who	1									
	cannot afford to live in Mariemont (who don't want 32										
	coming thru their area) and want to do things in Cincinnati.	-									
	Oasis line commuter rail from Clermont County to Cincinnati Riverfront.										
Access	Metro line. (2 pins)	-									
	Light rail is needed.										
Round Bottom Road: SR 3	32 to Valley										
Congestion	Ridiculous backups going to east SR 32. This backs up to the	none	n/a	n/a	n/a	No crashes along segment from 2013	n/a		No deficiencies	Address congestion.	none
	car wash at times. Essentially Newtown is gridlock. (2 pins)					through 2015. Not identified as a		queues from the			
	From 32 to Round Bottom to Wooster, very slow. I know					high hazard location by ODOT screening.		Round Bottom Road intersection			
	bypass is dead but something needs to be done.					Jercennig.		impacts the	<u>'</u>		
	Congestion issue. (2 pins)							southbound			
	Congestion waiting to get onto 32. (4 pins)							direction of this			
Congestion/Access	Improved roadway as an alternative east-west route.	-						segment			
Safety	Nobody takes this curve appropriately. I've been rear-ended										
Safety	here twice by people who don't yield.  Round Bottom, not safe to drive, (let) alone walk or ride bike.	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	Enhance bicycle connectivity.
Surcey	There is a park in the area. (4 pins)		1,10	.,, 0	.,,	.,, 0	li, u	.,,	.,, .		Limiting bicycle confidentially.
Mobility	Need marked bike lanes. (4 pins)										
Safety/Mobility	Provide Multi-modal paths into Clermont County and										
	discourage bicycle traffic along Round Bottom Road absent a										
Safaty	significant safety upgrade.  Safety concern. (2 pins)	-									
Safety Safety	Round Bottom, not safe to drive, (let) alone walk or ride bike.	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
	There is a park in the area.		.,, -	1.7.2	,2	1,72	"	.,, =	1.72		
	Safety concern										
Access/Mobility	I would love to see more rail and local bus access in the	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
	suburbsLess driving means less pollution coming from cars.										
Access/Mobility	Need park and ride. (2 pins)	-									
Round Bottom/Valley Int						1					
Congestion	none	none	AM NBL = Queue > Storage	AM NBL = Queue > Storage	AM NBL = Queue > Storage	No crashes at intersection from 2013	n/a	n/a	No deficiencies	Address capacity issues for	none
			AM NBL = LOS F, v/c 1.02		AM NBL = LOS F, v/c 1.02	through 2015. Not identified as a				northbound left turn movement and	
			PM EBL = Queue > Storage	AM EBR = LOS F, v/c 0.91	AM EBR = LOS F, v/c 0.93	high hazard location by ODOT				eastbound approach.	
					PM EBL = Queue > Storage	screening.					
Round Bottom: Valley to	Broadwell										
Congestion	Slows to 35-25 MPH. Traffic lights are slow. Roads are small.	none	n/a	n/a	n/a	7 crashes along segment from 2013	n/a	n/a	Deficient horizontal	none	Correct deficient roadway curve near
	Too much congestion.					through 2015. Not identified as a			degree of curvature in		Natorp's Nursery.
	There is too much traffic here and dangerous traffic.					high hazard location by ODOT			front of Natorp's		
	Anderson Township cannot add to it with a limestone mine.					screening.			Nursery.		
Safety	2 lane road, bicyclists go slowly on this windy road. Need a	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	Enhance bicycle connectivity.
	bike lane if possible.  Round Bottom too narrow for bike traffic.	-									
Mobility	Bike lane along Round Bottom.	+									
Safety	Too high speed limit on too narrow road.	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
Valley Avenue											
Congestion	Too many stop and go situations.	none	n/a	n/a	n/a	3 crashes along segment from 2013	n/a	n/a	No deficiencies	none	none
	Long backups for people trying to get to SR 32.					through 2015. Not identified as a					
	Newtown is awful to drive through. It needs a bypass as there					high hazard location by ODOT					
	is no over way to get to east SR 32 without driving way out of					screening.					
	the way.  Many of us take Valley to Round Bottom to avoid Church	+									
	Street. This is always slow during peak hours.										
	Green light (vs. dedicated green-arrow) turns used instead.										
	Always congested turning onto Valley Avenue.										
	This light creates problems and the 25 mph on Valley does as well.										
Church (Newtown): SR 32											
		Inone	ln/2	ln/2	ln/2	2 craches along cogness from 2012	100/ incres	DM nook have	Deficient vertical	Addross porthbound ANA and	Addross roadway grades at mailman
Congestion	Congestion Issue. (4 pins)  Too much congestion in Newtown even on weekends. A	none	n/a	n/a	n/a	3 crashes along segment from 2013 through 2015. Not identified as a	in the NB	· ·		Address northbound AM and southbound PM peak-hour delays.	Address roadway grades at railroad crossing.
	bypass is needed.					high hazard location by ODOT			tracks.	Toda ti Toda Pedik-Hour delays.	
	Four bad intersections, poor traffic flow: 1) Valley/Church, 2)					screening.	during the AM				
							peak-hour and	impacts the			
	Valley/Round bottom, 3) Church/Batavia, 4) Batavia/Round				_		F00/:			-	
	bottom.							southbound			
	bottom. Always congested turning onto Valley from Church.						in the SB trave	direction of this			
	bottom.  Always congested turning onto Valley from Church.  Rush hour gridlock.						in the SB trave time during	direction of this			
	bottom. Always congested turning onto Valley from Church.						in the SB trave	direction of this			

**HCS Analysis** 

T	Matua Quant Carramanta	Workshop Comments	Frieting Voor 2015	HCS Analysis	Design Veer 2042	Cafat.	Tuescal Times	Outaina Amalicaia	Coometrie Analysis	Duimanus Na ada	Consendant Nondo
<u>Transportation Concern</u>	MetroQuest Comments  Round Bottom, Valley, and Church Streets cannot handle	Workshop Comments	Existing Year 2015	Opening Year 2022	Design Year 2042	Safety	Travel Time compared to	Queue Analysis	Geometric Analysis	Primary Needs	Secondary Needs
	traffic volume.						the off-peak				
Other-Maintenance	Needs repair; rail crossing not level						travel time.				
Mobility	Roadway system in Newtown is confusing. Needs to be										
	improved to make clearer to traveling public. Signal										
	improvements or possible roundabout at Church Street at										
	Shell Station should be considered.										
Access											
	I think it would make sense to post train schedules on a sign										
	on each side of the crossing, so that deliveries, commuters, and emergency services would benefit by knowing ahead of										
	time. If schedules vary all over the place, it makes no sense.										
Safety/Mobility	Little Miami Trail just ends and then it is scary to be on the	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	Enhance bicycle connectivity.
	road with all of the vehicle traffic.										
	Best if bikes have a designated lane on streets, or else specific										
	bike paths.										
Mobility	Better bike path on Church from SR 32 to bike trail near Columbia Parkway.										
Access	Connect to 5 mile trail.	-									
7.00033	Should have good connecting paths from the bike trail to	-									
	Newtown and Clear Creek Park.										
Mobility	•	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
	and local shopping.										
Access/Mobility	Do not increase traffic at any point along Ohio River-to-Erie										
Access	Trail.	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	Support access to future transit
Access/Mobility	Potential rail stop.  Need accessible transit stop. (2 pins)	-	, u	.,, 0	.,, a	.,, 5	1.7 u	11, 4	11,0	none	connections.
Access/Mobility	Need rail service from eastern communities (Mariemont,	-									
	Newtown, Milford, & Eastgate) to downtown.										
	Need bus service.										
	Newtown Station Oasis Line.										
	Newtown is a walkable village. Therefore, it makes sense to										
	have public transit options that do not add vehicular traffic or the roads.										
Mobility	Utilizing Oasis Line for commuter rail.	-									
Church (Newtown) /Valle											
Congestion	Traffic Signal Issue. This light creates problems. And the 25	none	No deficiencies	PM SBL = Queue > Storage	PM SBL = Queue > Storage	No crashes at intersection from 2013	l In/a	n/a	No deficiencies	Address capacity issues for	none
	mph on Valley does as well.				The state of the s	through 2015. Not identified as a		1,72		southbound left-turn movement.	1000
	Slows to 25 mph. Traffic lights are slow. Roads are small.				PM SBL = LOS F, v/c 1.04	high hazard location by ODOT					
	Too much congestion.					screening.					
	Traffic Signal Issue. This intersection is congested. A simple										
	improvement would be a green right turn arrow for when traffic on Church Street has a left turn arrow. This will safely										
	allow for a quicker traffic flow.										
	This is where the backup starts just to get through the first	1									
	light.										
Church (Newtown): Valley	to US 50										
Congestion	Congestion issue. (4 pins)	none	n/a	n/a	n/a	6 crashes along segment from 2013	40% increase	n/a	No deficiencies	Address northbound AM and	none
	Congestion from Newtown to Mariemont.	_				through 2015. Not identified as a	in the NB			southbound PM peak-hour delays.	
	This is typically congested during the evening commute.					high hazard location by ODOT	travel time				
	During very busy times or if there is an accident or flooding, it becomes a dead stop. Probably because it's one of the only					screening.	during the AM peak-hour and				
	ways to cross the river.						a 50% increase				
	There are only two links between 50 and 32. Beechmont,						in the SB trave				
	which is a multi-lane parkway, and Newtown Road/Church						time during				
	Street. With only two options, many end up taking the single						the PM peak-				
	lane in each direction.						hour				
	Getting in and out of parking lots along Newtown Road is						compared to the off-peak				
	difficult.  Backed up traffic.	_					travel time.				
	Too congested.	-									
	Too much traffic during rush hour. I avoid this area at all cost										
	Improve current options to cross the Miami River.	-									
	The only viable bridge over the river is now here. ODOT has										
	abandoned all other possibilities. This intersection and bridge need a complete redesign to handle far great traffic.										
		-									
	Make four lanes from Valley to US 50.  Congested from Newtown to Mariemont. (4 pins)										
Safety	Needs Repair, road is in bad shape.										
Access	Missing Connection. Put in a service road for local traffic. Put	t e									
	in a straight shot over to the SR 32 bypass going around										
	Newtown allowing traffic to flow more freely off 50 and off of										
	SR 32.	-									
	Better connection to 32										

				<b>HCS Analysis</b>							
<b>Transportation Concern</b>	MetroQuest Comments	Workshop Comments	Existing Year 2015	Opening Year 2022	Design Year 2042	Safety	Travel Time	<b>Queue Analysis</b>	<b>Geometric Analysis</b>	Primary Needs	Secondary Needs
Mobility	Current roadway, no additional expansion needed and no										
	addition impact on protected river allowed.										
Congestion	Do not increase traffic at any point along Ohio River-to-Erie	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
	Trail.										
Access	Finish/connect bike trail to Cincinnati										
Access/Mobility	A path starts here. This should be extended.										
	The bike path really doesn't connect anything. It would be far										
	more useful if it connected to downtown. It also lacks										
	connections to the road system.										
	Bicycle lanes or path connecting Little Miami Trail to Murray										
	Road Trail.										
	I would like to see the bike trail on Newtown Road connected	d d									
	to downtown, also through Mariemont, Fairfax, and Hyde										
	Park.										
Mobility	Need bike path.									A second	
	Continue to enhance existing bike trail.										
	Need bike path; need a convenient and safe path to get from										
	here (Newtown bridge) to Downtown; add bike path to get to										
	Miami bluff road										
	Need bike path; extend bike path and connect to Wasson Way	/									
Mobility	Need sidewalk.	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
Mobility/Safety	Safe Pedestrian/bike lanes needed.										
Access/Mobility	Need bus service.	none	n/a	n/a	n/a	n/a	n/a	n/a	n/a	none	none
	This would be a great stop for a Park and Ride. I wouldn't										
	want to turn this nice green space into a parking lot, but a										
	hidden parking garage could possibly fit somewhere.										
Mobility	Local bars and restaurants (i.e., brewery) and not everyone										
	uses UBER to get home.										

Roadway
Pedestrian
Bicycle
Transit