

Eastern Corridor Segments II and III

Village of Newtown Focus Area

LEGEND

Identified Primary Need: Will Be Addressed By Project
Identified Secondary Need: May Be Addressed By Project

Anderson Twp.

Columbia Twp.

Newtown Road: Valley Avenue to US 50

Address northbound AM and southbound PM peak-hour delays

Church Street (Newtown Road)/Valley Avenue Intersection

Address capacity issues for southbound left-turn movement

Church Street: SR 32 to Valley Avenue

- Address northbound AM and southbound PM peak-hour delays
- Address roadway grades at railroad crossing
- Enhance bicycle connectivity
- Support access to future transit connections

SR 32/Church Street Intersection

Address capacity issues and long queues on all approaches

Round Bottom Road: Valley Avenue to Broadwell Road

- Correct deficient roadway curve near Natorp's Nursery
- Enhance bicycle connectivity

Anderson Twp.

Round Bottom Road/Valley Avenue Intersection

Address capacity issues with northbound left-turn movement and eastbound approach

Round Bottom Road: SR 32 to Valley Avenue

- Address congestion
- Enhance bicycle connectivity

SR 32: Round Bottom Road to Little Dry Run Road

- Address westbound AM peak-hour and eastbound PM peak-hour delays
- Address pedestrian connectivity to east corporation limit
- Address bicycle connectivity
- Support access to future transit connections

SR 32/Round Bottom Road Intersection

- Address capacity issues and long queues on SR 32 and Round Bottom Road approaches
- Address deficient sight distance at intersection

SR 32: Church Street to Round Bottom Road

- Address westbound AM peak-hour and eastbound PM peak-hour delays
- Address bicycle connectivity

SR 32: West Corporation Limit to Church Street

- Address eastbound PM peak-hour delays
- Address bicycle connectivity

